



CF-1 CABOOSE FLASHER

The CF-1 is powered by a 9 volt battery. Mount the LED first. Bend the leads flush with the LED body, if desired. Note the marking on the LED lead or the color band may be on the LED body.



Solder the WHITE lead from the circuit board to the cathode of the LED. The ORANGE lead goes to the anode. Use needlenose pliers to hold the lead near the body while soldering to avoid heat damage. The RED and BLACK leads connect to a 9 volt battery. RED is positive.



CIRCUITRON, INC., Romeoville, IL 60446